OCCHEDENTIAL

OUT60486

P 252312Z NOV 66 FM NPIC WASH DC TO AIG NINE SEVEN SIX RUEKDA/DIA PRODCEN RUEKDA/NIC BT C O N F I D E N T I A L CITE NPIC 9150.	1966 NOV 25	28 NUV 1966 23 30 Z  DISTRIBUTION Z  Of the Action os see br
REF A NPIC 8603, DTG 280001Z, SEPT 1966  B NPIC 8904, DTG 290007Z, OCT 1966  INITIAL SCAN BY NPIC OF MISSION		TDS  3 (SD)  1PD  1PD  1PD  1PSD  1AD  25X1
REVEALS THE PREVIOUSLY REPORTED SERVICEABLE DATE AND HIGHWAY BRIDGE OVER THE SONG CAU  10605E (REF A) TO BE UNSERVICEABLE. TWO SPANS HAVE ONE SPAN HAS BEEN DISLOCATED. AND THE NORTHERN APPRO	AT 2112N BEEN DESTRO	PAG 25X1_DIAXX-5 SPAD 25X1-DIA-AP
INTERDICTED. THE RAIL BY-PASS BRIDGE AT XJ131457 HAS OBSERVED OPERATIONAL BECAUSE OF REMOVED SPANS, A TECTOR OF THE MISSING SPANS ON THE BY-PASS BRIDGE ARE IN THE I	AS NEVER BEI CHNIQUE PREV	Sanilizad X EN VIOUSLY
EMPLACED. ONLY ONCE SPAN IS NOW MISSING AND IT IS IN LARGE AF I NURTH OF THE BRIDGE AT UTM XJ132459. ON TWO SPANS WERE MISSING THEY WERE	PHOTOGRAPHY E LOCATED ON	OF THE 25X1
SOUTH BANK OF THE RIVER AT UTM'S XJ132459 AND XJ1304 RAFT WAS LOCATED AT UTM XJ129463. (BB) MAP REF: AMS SERIES L7014 SHEET 6251 III	461 AND A LA	ARGE 25X1
USATC SERIES 200 SHEET 0616-20HL GP-1		

CONFIDENTIAL CENDOFFICESSAGE-S/C NOTE: ALSO PASSED PRIORITY SAIGON INFO DIRECTOR, VIENTIANE,
UDORN CITE NP Approved For Release 2008/03/12: CIA-RDP78B04558A001500010018-6